

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 5/15/2014 Time: 10:24 AM
Name of School Corporation: M.S.D. MARTINSVILLE SCHOOLS Corp ID: 555925
Address of School Corporation: PO Box 1416
City: Martinsville Zip: 46151 County Number: 55
VIN: 4DRBRABN73B947070 License Number: 5252 Bus Number: 162
Make of Body: AmTran Year: 2003 Make of Chassis: IC Corporation Year: 2003
Bus Type: C Mileage: Unknown
Inspection Status: O Inspected By: Mark Raper PE: 6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
15-1-1	There are leaks from the differential, pinion seal, or either rear wheel seal.
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
11-1-2	The front or rear bumper is not properly attached.
11-1-1	The front bumper does not extend to the edge of the fenders.
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
24-1-1	Mirror or mirror backs are loose or improperly mounted.
33-1-1	Headlight is inoperative.
63-1-1	Turn signals are not properly mounted
63-1-4	Front turn signal does not function properly
63-1-2	A lens is cracked, missing or wrong color
32-1-2	The grill is missing.
32-1-1	The grill has any exposed edges that may cause injury.
50-1-1	Door seals are missing, damaged, or torn.
69-1-4	There is cracked glass to the immediate right or left of the driver
35-1-1	The latch does not secure the hood tightly.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
7-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
24-2-2	Reflective glass is cracked, broken, or missing.

24-2-1
38-2-1
50-2-1
69-2-1
35-2-1

Mountings are broken or bent badly enough to inhibit proper adjustment.
Inner fenders are loose from body or mounting brackets.
The service door does not open or close properly
Glass or glazing is broken through or missing
The latch mechanism is missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.