

REPORT OF SCHOOL BUS INSPECTION

| | | | |
|--|-------------------------------------|-----------------------------------|-------------------|
| Type of Inspection: Registration | Date: 5/20/2014 | Time: 12:17 PM | |
| Name of School Corporation: CULVER EDUCATIONAL FOUNDATION | Corp ID: 50001Z | | |
| Address of School Corporation: 1300 Academy Rd 154 | | | |
| City: Culver | Zip: 46511 | County Number: 50 | |
| VIN: 1GB3G3BG3D1144795 | License Number: B669J | Bus Number: 104 | |
| Make of Body: Chevrolet | Year: 2013 | Make of Chassis: Chevrolet | Year: 2013 |
| Bus Type: A1 | Mileage: Unknown | | |
| Inspection Status: A | Inspected By: Travis Harrold | PE: 8022 | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**