## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection**: Annual **Date**: 5/20/2014 **Time**: 12:22 PM **Name of School Corporation**: RIVER FOREST COMM. SCHOOL CORP **Corp ID**: 454590

Address of School Corporation: 3250 Michigan St

 City:
 Hobart
 Zip:
 46342
 County Number: 45

 VIN:
 1HVBJAAR22A919921
 License Number: 18463
 Bus Number: 8

 Make of Body:
 AmTran Year: 2002
 Make of Chassis: AmTran Year: 2002
 Year: 2002

Bus Type: D Mileage: Unknown

Inspection Status: O Inspected By: Nathan Sherer PE: 7029

## **Violations - Rejected**

<u>Inspection Code</u> <u>Description</u>

63-1-4 Front turn signal does not function properly

## **Violations - Out of Service**

<u>Inspection Code</u> <u>Description</u>

63-2-1 Rear turn signal does not function properly

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.