

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/19/2014	<b>Time:</b>	10:56 AM
<b>Name of School Corporation:</b>	LAPORTE COMMUNITY SCHOOL CORP.			<b>Corp ID:</b>	464945
<b>Address of School Corporation:</b>	1000 Harrison St				
<b>City:</b>	La Porte	<b>Zip:</b>	46350	<b>County Number:</b>	46
<b>VIN:</b>	4UZABRDC38CZ10884	<b>License Number:</b>	31238	<b>Bus Number:</b>	7
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown	<b>Year:</b>	2008
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	David Eggers	<b>PE:</b>	5191

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
47-1-2	There are loose lines, fittings or hoses.
40-1-2	Interior protrusions have sharp edges or corners.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**