

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/28/2014	<b>Time:</b> 1:36 PM
<b>Name of School Corporation:</b> CANNELTON CITY SCHOOLS	<b>Corp ID:</b> 626340	
<b>Address of School Corporation:</b> 109 S 3rd St		
<b>City:</b> Cannelton	<b>Zip:</b> 47520	<b>County Number:</b> 62
<b>VIN:</b> 1GBJG31K691162866	<b>License Number:</b> 81444	<b>Bus Number:</b> 3
<b>Make of Body:</b> Collins Bus Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2009	<b>Mileage:</b> Unknown	<b>Year:</b> 2009
<b>Bus Type:</b>		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Kelly Hammond	<b>PE:</b> 6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-2	Wiper blades fail to contact the windshield properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------