## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual 6/3/2014 **Time**: 7:45 AM Date:

Name of School Corporation: GREATER JASPER CONS. SCHOOLS 192120 Corp ID:

**Address of School Corporation:** 1520 Saint Charles St

City: Jasper Zip: 47546 **County Number: 19** VIN: 1GB3G3BG0B1118569 License Number: 11489 **Bus Number:** Chevrolet Year: 2011 Make of Chassis: Chevrolet Year: 2011 Make of Body:

Bus Type: Unknown Mileage:

Inspection Status: R **Inspected By:** Kelly Hammond PE: 6682

## Violations - Rejected

## **Inspection Code Description**

27-1-1 The first aid kit is not properly displayed.

Required padding is missing. 19-1-6

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**