REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/2/2014	**Time:**	8:32 AM
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS			**Corp ID:**	475075
Address of School Corporation:	595 Stars Blvd				
City:	Bedford	**Zip:**	47421	**County Number:**	47
VIN:	1FDXB80C3TVA20862	**License Number:**	15283	**Bus Number:**	A9
Make of Body:	Carpenter **Year:** 1997	**Make of Chassis:**	Ford	**Year:**	1997
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Travis Coryea	**PE:**	5892

Violations - Rejected

Inspection Code	Description
52-1-1	One (1) leaf spring is broken under the first two (2) leaves

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.