REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	6/12/2014	**Time:**	10:39 AM
Name of School Corporation:	SOUTH HARRISON COMM. SCH. CORP					**Corp ID:**	313190
Address of School Corporation:	315 S Harrison Dr						
City:	Corydon	**Zip:**	47112			**County Number:**	31
VIN:	4DRBRABP04B961542			**License Number:**	19424	**Bus Number:**	57A
Make of Body:	IC Corporation	**Year:**	2004	**Make of Chassis:**	IC Corporation	**Year:**	2004
Bus Type:	B			**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Troy Boyd			**PE:**	5171

Violations - Rejected

Inspection Code	Description
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
67-1-1	Washers do not function properly in any manner

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.