

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/12/2014	<b>Time:</b>	10:39 AM
<b>Name of School Corporation:</b>	SOUTH HARRISON COMM. SCH. CORP			<b>Corp ID:</b>	313190
<b>Address of School Corporation:</b>	315 S Harrison Dr				
<b>City:</b>	Corydon	<b>Zip:</b>	47112	<b>County Number:</b>	31
<b>VIN:</b>	4DRBRABP04B961542	<b>License Number:</b>	19424	<b>Bus Number:</b>	57A
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2004	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	B	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Troy Boyd	<b>PE:</b>	5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
67-1-1	Washers do not function properly in any manner

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**