

# REPORT OF SCHOOL BUS INSPECTION

|  |                                   |                 |               |                  |                         |       |      |
|--|-----------------------------------|-----------------|---------------|------------------|-------------------------|-------|------|
| Type of Inspection:                            | Annual                            | Date:           | 6/18/2014     | Time:            | 10:57 AM                |       |      |
| Name of School Corporation:                    | SCHOOL CITY OF HOBART SERVICE CTR |                 |               | Corp ID:         | 454730                  |       |      |
| Address of School Corporation: 200 S Hobart Rd |                                   |                 |               |                  |                         |       |      |
| City:  | Hobart                            | Zip:            | 46342         | County Number:   | 45                      |       |      |
| VIN:   | 1GBHG31K481214001                 | License Number: |               | 31447            | Bus Number:             | 42    |      |
| Make of Body:                                  | Chevrolet                         | Year:           | 2008          | Make of Chassis: | Collins Bus Corporation | Year: | 2008 |
| Bus Type:                                      | A1                                | Mileage:        |               | Unknown          |                         |       |      |
| Inspection Status:                             | R                                 | Inspected By:   | Nathan Sherer |                  | PE:                     | 7029  |      |

## Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 10-1-1                 | A parking brake lever is not allowed, a plastic/composite material allowing the parking brake knob to be larger and easier to pull is allowed. |

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.