

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	6/17/2014	Time:	11:54 AM
Name of School Corporation:	SOUTHWESTERN CON SCH SHELBY CO	Corp ID:	737360		
Address of School Corporation:	3406 W 600 S				
City:	Shelbyville	Zip:	46176	County Number:	73
VIN:	4UZ3CJAA1XCB74670	License Number:	B571b	Bus Number:	2
Make of Body:	Thomas Built Buses, Inc.	Year:	1999	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached.
11-1-1	The front bumper does not extend to the edge of the fenders.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-11	Any defect not in compliance with the minimum school bus brake inspection standards.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.