# REPORT OF SCHOOL BUS INSPECTION

Type of 10:25 Time: Annual Date: 7/1/2014 Inspection: AM Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750 **Address of School Corporation:** 2 S 3rd St. County City: Flora Zip: 46929 8 Number: License VIN: 1HVBBAAP04H657452 20344 **Bus Number:** 14 Number: Make of IC Blue Bird Year: 2004 2004 Make of Body: Year: Corporation Corporation Chassis: **Bus Type:** С Mileage: Unknown Inspection Inspected 0 PE: Nate King 7421 Status: By:

### **Violations - Rejected**

### Inspection Code Description

51-1-1 There are loose, broken, or missing mountings

15-1-1 There are leaks from the differential, pinion seal, or either rear wheel seal.

# **Violations - Out of Service**

#### **Inspection Code Description**

# **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.