## REPORT OF SCHOOL BUS INSPECTION

Type of 12:06 Time: Annual Date: 7/9/2014 Inspection: РМ Name of School Corporation: M.S.D. STEUBEN COUNTY 767615 Corp ID: **Address of School Corporation:** 400 S Martha St County City: Angola Zip: 46703 76 Number: License VIN: 4UZABRDJ7ACAN7509 32250 Bus Number: 10 Number: Thomas Built Buses, Year: 2010 Thomas Built Buses, Year: Make of Make of Body: 2010 Chassis: Inc. **Bus Type:** С Mileage: Unknown Inspection Inspected R PE: Eric Egbert 7006 Status: By:

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

43-1-1 Marker light or lens is missing, cracked, faded, wrong color, or inoperative.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.