

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	7/24/2014	<b>Time:</b>	9:17 PM
<b>Name of School Corporation:</b>	EVANSVILLE-VANDERBURGH SCH COR			<b>Corp ID:</b>	827995
<b>Address of School Corporation:</b>	951 Walnut St				
<b>City:</b>	Evansville	<b>Zip:</b>	47713	<b>County Number:</b>	82
<b>VIN:</b>	4UZABRDK9ACAN8833	<b>License Number:</b>	31879	<b>Bus Number:</b>	11
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Bradley Miller	<b>PE:</b>	7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-2	Leaf spring extends more than 1/4 inch beyond the vertical alignment of the spring stack

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**