REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 7/28/2014 Time: 9:01 AM Name of School Corporation: SOUTH BEND COMM. SCHOOL CORP. Corp ID: 717205

Name of School Corporation: SOUTH BEND COMM. SCHOOL CO
Address of School Corporation: 3003 N Bendix Dr

City:South BendZip:46601County Number: 71VIN:4DRBUAAP6AB142191License Number: temp456653Bus Number: 55Make of Body:IC Corporation Year: 2010Make of Chassis: IC Corporation Year: 2010

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Travis Harrold PE: 8022

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

Rear tire has less than 2/32 inch tread depth when measured in a major groove.

12-1-1 Clearance light is missing, cracked, faded, wrong color, or inoperative.

Violations - Out of Service

Inspection Code	<u>Description</u>
22-2-1	Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.