REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/28/2014	**Time:**	9:01 AM
Name of School Corporation:	SOUTH BEND COMM. SCHOOL CORP.			**Corp ID:**	717205
Address of School Corporation:	3003 N Bendix Dr				
City:	South Bend	**Zip:**	46601	**County Number:**	71
VIN:	4DRBUAAP6AB142191	**License Number:**	temp456653	**Bus Number:**	55
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2010
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
62-1-4	Rear tire has less than 2/32 inch tread depth when measured in a major groove.
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.

Violations - Out of Service

Inspection Code	Description
22-2-1	Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.