REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	7/30/2014	**Time:** 9:17 AM
Name of School Corporation:	NORTHEAST SCHOOL CORPORATION				**Corp ID:** 777645
Address of School Corporation:	PO Box 493				
City:	Hymera	**Zip:**	47855		**County Number:** 77
VIN:	4DRBUAAN19B042641		**License Number:**	31506	**Bus Number:** 25
Make of Body:	IC Corporation **Year:** 2009		**Make of Chassis:**	IC Corporation	**Year:** 2009
Bus Type:	C		**Mileage:**	Unknown	
Inspection Status:	O	**Inspected By:**	Tyler VanNess		**PE:** 7583

Violations - Rejected

Inspection Code	Description
61-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

Inspection Code	Description
63-2-1	Rear turn signal does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.