

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|--------------------------|-----------------|----------------|------------------|--------------------------|-------|------|
| Type of Inspection: | Annual | Date: | 7/31/2014 | Time: | 9:12 AM | | |
| Name of School Corporation: | M.S.D. MOUNT VERNON | | | Corp ID: | 656590 | | |
| Address of School Corporation: | 1000 W 4th St | | | | | | |
| City: | Mt Vernon | Zip: | 47620 | County Number: | 65 | | |
| VIN: | 4UZAAXC563CK91996 | License Number: | B473D | Bus Number: | 17 | | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2003 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2003 |
| Bus Type: | C | Mileage: | Unknown | | | | |
| Inspection Status: | O | Inspected By: | Bradley Miller | PE: | 7809 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 54-2-5 | There is movement in a spring loaded drag link greater than 1/8 inch |
| 7-2-4 | Any brake line or hose is abraded (chafed), cracked, bulging or leaking. |
| 7-2-6 | There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely. |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.