

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/4/2014	Time: 9:54 AM
Name of School Corporation: AVON COMMUNITY SCHOOLS	Corp ID: 323315	
Address of School Corporation: 7203 E HWY 36		
City: Avon	Zip: 46123	County Number: 32
VIN: 4DRBWAAR08A642729	License Number: 31777	Bus Number: 132
Make of Body: IC Corporation	Year: 2008	Make of Chassis: IC Corporation
Year: 2008	Mileage: Unknown	Year: 2008
Bus Type: D		
Inspection Status: R	Inspected By: John Pang	PE: 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
21-1-1	A dripping oil or fluid leak.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.