REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/7/2014	**Time:**	10:21 AM
Name of School Corporation:	NORTH WEST HENDRICKS SCHOOLS			**Corp ID:**	323295
Address of School Corporation:	PO Box 70				
City:	Lizton	**Zip:**	46149	**County Number:**	32
VIN:	4DRBUAFPX8B556786	**License Number:**	796	**Bus Number:**	4
Make of Body:	AmTran **Year:** 2008	**Make of Chassis:**	IC Corporation	**Year:**	2008
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.