## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection**: Annual **Date**: 8/22/2014 **Time**: 12:21 AM **Name of School Corporation**: BETHESDA BAPTIST CHURCH & SCHOOL **Corp ID**: 323318

Address of School Corporation: 7950 N CR 650 E

City:BROWNSBURGZip:46112County Number:32VIN:1GDL7T1E82J509458License Number:Bus Number:1Make of Body:GMCYear:2002Make of Chassis:GMCYear:2002

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Edwin Davis PE: 3981

## **Violations - Rejected**

Inspection Code	<u>Description</u>
63-1-4	Front turn signal does not function properly
42-1-2	Required lettering is missing or faded.
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.
21-1-1	A dripping oil or fluid leak.

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
7-2-1	There is no brake certification, the certification is expired, or is not signed within the
	six-month requirement.

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.