

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/4/2014	Time: 8:27 AM
Name of School Corporation: CENTER GROVE COMM. SCHOOL CORP	Corp ID: 414205	
Address of School Corporation: 4900 W Stones Crossing Rd		
City: Greenwood	Zip: 46143	County Number: 41
VIN: 4DRBJABN43A952465	License Number: 19354	Bus Number: 64
Make of Body: IC Corporation	Year: 2003	Make of Chassis: IC Corporation
Year: 2003	Mileage: Unknown	Year: 2003
Bus Type: D		
Inspection Status: O	Inspected By: John Pang	PE: 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-2	There are intersecting cracks in the windshield area covered by the wipers
56-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
69-2-1	Glass or glazing is broken through or missing
50-2-1	The service door does not open or close properly
56-2-1	Part of the step-well or support structure is rusted through

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.