

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 9/15/2014 **Time:** 10:15 AM
Name of School Corporation: DECATUR COUNTY COMM. SCHOOL **Corp ID:** 161655
Address of School Corporation: 1645 W SR 46
City: Greensburg **Zip:** 47240 **County Number:** 16
VIN: 1HVBBABPOXH207206 **License Number:** B455H **Bus Number:** 21
Make of Body: IC Corporation **Year:** 1999 **Make of Chassis:** IC Corporation **Year:** 1999
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-8	The electric power assist motor fails to operate.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.