## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	9/15/2014	Time:	11:44 AM
Name of School Corporation: Address of School Corporation:		DECATUR COUNTY COMM. SCHOOL 1645 W SR 46			Corp ID:	161655	
City:	Greensburg		Zip:	47240		County Number:	16
VIN:	1HVBBABP7XH240574		License Number:	B839G	Bus Number:	34	
Make of Body:	Blue Bird Corporation	Year:	1999	Make of Chassis:	IC Corporation	Year:	1999
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	R		Inspected By:	Chris Clark		PE:	6665

# **Violations - Rejected**

Inspection Code	<u>Description</u>
23-1-5	Paint is badly faded or peeling.
21-1-1	A dripping oil or fluid leak.
43-1-1	Marker light or lens is missing, cracked, faded, wrong color, or inoperative.

### **Violations - Out of Service**

## **Inspection Code Description**

# **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.