

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/23/2014	Time: 2:16 PM	
Name of School Corporation: RICHLAND-BEAN BLOSSOM C.S.CORP	Corp ID: 535705		
Address of School Corporation: 600 S Edgewood Dr			
City: Ellettsville	Zip: 47429	County Number: 53	
VIN: 4DRBWAAR76A245001	License Number: 21306	Bus Number: 18	
Make of Body: IC Corporation	Year: 2006	Make of Chassis: IC Corporation	Year: 2006
Bus Type: D	Mileage: Unknown		
Inspection Status: A	Inspected By: Mark Raper	PE: 6473	

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.