

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 9/23/2014 **Time:** 2:16 PM
Name of School Corporation: RICHLAND-BEAN BLOSSOM C.S.CORP **Corp ID:** 535705
Address of School Corporation: 600 S Edgewood Dr
City: Ellettsville **Zip:** 47429 **County Number:** 53
VIN: 4DRBWAAR76A245001 **License Number:** 21306 **Bus Number:** 18
Make of Body: IC Corporation **Year:** 2006 **Make of Chassis:** IC Corporation **Year:** 2006
Bus Type: D **Mileage:** Unknown
Inspection Status: A **Inspected By:** Mark Raper **PE:** 6473

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.