REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	9/25/2014	**Time:**	8:36 AM
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.			**Corp ID:**	414225
Address of School Corporation:	750 E SR 44				
City:	Franklin	**Zip:**	46131	**County Number:**	41
VIN:	1HVBRAAPX2A920824	**License Number:**	18360	**Bus Number:**	150
Make of Body:	IC Corporation **Year:** 2002	**Make of Chassis:**	IC Corporation	**Year:**	2002
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
66-1-2	Rims are bent or loose
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
52-1-3	Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
30-1-1	There are loose or missing bolts or rivets where front and rear spring hangers are attached to the frame.

Violations - Out of Service

Inspection Code	Description
52-2-4	Shackles are worn, loose, broken, cracked or missing
52-2-5	"U" bolts are loose, broken, or missing
52-2-1	Broken main leaf in a leaf spring.
52-2-2	Two (2) leaf springs (other than the top two (2) leaves) are broken
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
62-2-3	Tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.