

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/25/2014	Time: 8:36 AM
Name of School Corporation: FRANKLIN COMM. SCHOOL CORP.	Corp ID: 414225	
Address of School Corporation: 750 E SR 44		
City: Franklin	Zip: 46131	County Number: 41
VIN: 1HVBRAAPX2A920824	License Number: 18360	Bus Number: 150
Make of Body: IC Corporation	Year: 2002	Make of Chassis: IC Corporation
Year: 2002	Mileage: Unknown	Year: 2002
Bus Type: C		
Inspection Status: O	Inspected By: John Pang	PE: 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-2	Rims are bent or loose
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
52-1-3	Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
30-1-1	There are loose or missing bolts or rivets where front and rear spring hangers are attached to the frame.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
52-2-4	Shackles are worn, loose, broken, cracked or missing
52-2-5	"U" bolts are loose, broken, or missing
52-2-1	Broken main leaf in a leaf spring.
52-2-2	Two (2) leaf springs (other than the top two (2) leaves) are broken
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
62-2-3	Tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.