REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	9/25/2014	**Time:**	9:23 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	4UZAAXBV62CJ97773	**License Number:**	D784792	**Bus Number:**	16
Make of Body:	Freightliner **Year:** 2002	**Make of Chassis:**	Freightliner	**Year:**	2002
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
7-1-1	Any push-rod travel measures less than 1/4 inch beyond the readjustment limit.
62-1-3	Any front tire has less than 4/32 inch tread depth when measured in a major groove.
21-1-2	The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.).
21-1-1	A dripping oil or fluid leak.
3-1-3	Battery is loose in its mounting.

Violations - Out of Service

Inspection Code	Description
7-2-1	There is no brake certification, the certification is expired, or is not signed within the six-month requirement.
69-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.