REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 9/25/2014 **Time**: 9:23 AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 City: Elnora Zip: 47529 **County Number: 14** VIN: 4UZAAXBV62CJ97773 **Bus Number:** License Number: D784792 16 Make of Body: Freightliner Year: 2002 Make of Chassis: Freightliner Year: 2002 Bus Type: С Mileage: Unknown Inspection Status: O PE: 6682 **Inspected By:** Kelly Hammond

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|--|
| 7-1-1 | Any push-rod travel measures less than 1/4 inch beyond the readjustment limit. |
| 62-1-3 | Any front tire has less than 4/32 inch tread depth when measured in a major groove. |
| 21-1-2 | The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.). |
| 21-1-1 | A dripping oil or fluid leak. |
| 3-1-3 | Battery is loose in its mounting. |

Violations - Out of Service

| Inspection Code | <u>Description</u> |
|--------------------|---|
| 7-2-1 | There is no brake certification, the certification is expired, or is not signed within the six-month requirement. |
| 69-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.