

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 9/25/2014 **Time:** 12:15 PM
Name of School Corporation: CARMEL CLAY SCHOOLS **Corp ID:** 293060
Address of School Corporation: 5185 E 131st St
City: Carmel **Zip:** 46032 **County Number:** 29
VIN: 4DRBWAAR8AA185173 **License Number:** 32802 **Bus Number:** 103
Make of Body: IC Corporation **Year:** 2010 **Make of Chassis:** IC Corporation **Year:** 2010
Bus Type: D **Mileage:** Unknown
Inspection Status: O **Inspected By:** Alex Willis **PE:** 4760

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.