# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Semi-Annual | | **Date:** 9/30/2014 | **Time:** | 9:10 AM |
| **Name of School Corporation:** | TRITON SCHOOL CORPORATION | | | **Corp ID:** | 505495 |
| **Address of School Corporation:** | 100 Triton Dr | | | | |
| **City:** | Bourbon | **Zip:** | 46504 | **County Number:** | 50 |
| **VIN:** | 1GBHG31R321147184 | | **License Number:** 33996 | **Bus Number:** | AB1 |
| **Make of Body:** | Thomas Built Buses, Inc. **Year:** 2002 | | **Make of Chassis:** Chevrolet | **Year:** | 2002 |
| **Bus Type:** | B | | **Mileage:** Unknown | | |
| **Inspection Status:** | A | **Inspected By:** | Travis Harrold | **PE:** | 8022 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**