REPORT OF SCHOOL BUS INSPECTION

Type of 9:05 Semi-Annual 10/7/2014 **Time**: Date: Inspection: AM Name of School Corporation: JOHN GLENN SCHOOL CORPORATION Corp ID: 717150 **Address of School Corporation:** 101 John Glen Dr County City: Walkerton Zip: 46574 71 Number: License VIN: 4UZ6CJAA7XCA36161 72446 **Bus Number:** 34 Number: Make of Blue Bird **Year:** 1999 Freightliner Year: Make of Body: 1999 Corporation Chassis: **Bus Type:** Mileage: 121921 Inspected Inspection Status: O Travis Harrold PE: 8022 By:

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection
CodeDescription7-2-4Any brake line or hose is abraded (chafed), cracked, bulging or leaking.7-2-2Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit.

Bus Type Description