REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:** 10/10/2014	**Time:**	1:02 PM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	4UZAAXBV62CJ97773		**License Number:** D784792	**Bus Number:**	16
Make of Body:	Freightliner **Year:** 2002		**Make of Chassis:** Freightliner	**Year:**	2002
Bus Type:	C		**Mileage:** Unknown		
Inspection Status:	O	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
21-1-2	The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.).
21-1-1	A dripping oil or fluid leak.
3-1-3	Battery is loose in its mounting.
7-1-1	Any push-rod travel measures less than 1/4 inch beyond the readjustment limit.
62-1-3	Any front tire has less than 4/32 inch tread depth when measured in a major groove.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.