REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:10/10/2014Time:1:03 PMName of School Corporation:NORTH DAVIESS CO. COMM. SCHOOLCorp ID:141375

Address of School Corporation: 5494 E SR 58

City:ElnoraZip:47529County Number:14VIN:1HVBRABP82A941296License Number:E198757Bus Number:12Make of Body:IC Corporation Year:2002Make of Chassis:IC Corporation Year:2002

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Kelly Hammond PE: 6682

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

19-1-8 If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.