

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/13/2014	Time:	1:24 PM
Name of School Corporation:	BROWNSBURG COMM. SCHOOL CORP.			Corp ID:	323305
Address of School Corporation:	310 Stadium Drive				
City:	Brownsburg	Zip:	46112	County Number:	32
VIN:	1T7YT4A2061165165	License Number:	9806	Bus Number:	77
Make of Body:	Thomas Built Buses, Inc.	Year:	2006	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	99165
Inspection Status:	R	Inspected By:	Edwin Davis	PE:	3981

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.