REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	10/15/2014	**Time:**	10:53 AM
Name of School Corporation:		RANDOLPH CENTRAL SCHOOL CORP.				**Corp ID:**	686825
Address of School Corporation:		103 N East St					
City:	Winchester	**Zip:**	47394			**County Number:**	68
VIN:	1T88R3B15Y1084451			**License Number:**	MO10889	**Bus Number:**	25
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2000	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2000
Bus Type:	D			**Mileage:**	165388		
Inspection Status:	O	**Inspected By:**	Jamie Hotchkiss			**PE:**	6458

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
62-2-3	Tire is flat
8-2-5	There is brake fluid leaking at any point.
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.