

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/15/2014	Time:	10:53 AM
Name of School Corporation:	RANDOLPH CENTRAL SCHOOL CORP.	Corp ID:	686825		
Address of School Corporation:	103 N East St				
City:	Winchester	Zip:	47394	County Number:	68
VIN:	1T88R3B15Y1084451	License Number:	MO10889	Bus Number:	25
Make of Body:	Thomas Built Buses, Inc.	Year:	2000	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:	165388		
Inspection Status:	O	Inspected By:	Jamie Hotchkiss	PE:	6458

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
62-2-3	Tire is flat
8-2-5	There is brake fluid leaking at any point.
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.