REPORT OF SCHOOL BUS INSPECTION

Type of 9:12 Semi-Annual 10/15/2014 **Time**: Date: Inspection: AM Name of School Corporation: SOUTH GIBSON SCHOOL CORP. Corp ID: 262765 **Address of School Corporation:** 1029 W 650 S County City: Fort Branch Zip: 47648 26 Number: License VIN: 1GBL7T1DXXJ105309 B473B **Bus Number:** 13 Number: Make of Blue Bird Year: 2000 Chevrolet Year: Make of Body: 2000 Corporation Chassis: **Bus Type:** С Mileage: 160265 Inspected PE: 7809 **Inspection Status:** R **Bradley Miller** By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

52-1-3 Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.