REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	10/15/2014	**Time:**	4:03 PM
Name of School Corporation:	SWITZERLAND COUNTY SCHOOL CORP			**Corp ID:**	787775
Address of School Corporation:	1040 W Main St				
City:	Vevay	**Zip:**	47043	**County Number:**	78
VIN:	4UZ3CFAA8YCF77043	**License Number:**	B768C	**Bus Number:**	C10
Make of Body:	Freightliner **Year:** 2000	**Make of Chassis:**	Freightliner	**Year:**	2000
Bus Type:	C	**Mileage:**	147273		
Inspection Status:	R	**Inspected By:**	Chris Clark	**PE:**	6665

Violations - Rejected

Inspection Code	Description
45-1-2	Seat back or bottom is loose.
23-1-1	The bus body has rust or rusted through areas which may weaken the body.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.