

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/16/2014 **Time:** 10:28 AM
Name of School Corporation: MARQUETTE HIGH SCHOOL **Corp ID:** 71002Z
Address of School Corporation: 306 W 10th St.
City: Michigan City **Zip:** 46306 **County Number:** 46
VIN: 1GBHG31R6Y1201361 **License Number:** b872aa **Bus Number:** 1
Make of Body: Chevrolet **Year:** 2000 **Make of Chassis:** Corbeil **Year:** 2000
Bus Type: **Mileage:** 96094
Inspection Status: R **Inspected By:** Dale Morgan **PE:** 4743

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.

Violations - Out of Service

Inspection Code Description

Bus Type Description