

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/16/2014	<b>Time:</b>	10:28 AM
<b>Name of School Corporation:</b>	MARQUETTE HIGH SCHOOL	<b>Corp ID:</b>	71002Z		
<b>Address of School Corporation:</b>	306 W 10th St.				
<b>City:</b>	Michigan City	<b>Zip:</b>	46306	<b>County Number:</b>	46
<b>VIN:</b>	1GBHG31R6Y1201361	<b>License Number:</b>	b872aa	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2000	<b>Make of Chassis:</b>	Corbeil
<b>Year:</b>	2000	<b>Mileage:</b>	96094	<b>Year:</b>	2000
<b>Bus Type:</b>					
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Dale Morgan	<b>PE:</b>	4743

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.
22-1-5	Any hanger, clamp or bracket is missing, loose or broken.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------