REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/21/2014 Time: 9:24 AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4UZ6CFAA7XCA45441License Number:Bus Number:10Make of Body:Freightliner Year:1999Make of Chassis:Freightliner Year:1999

Bus Type: C Mileage: 149613

Inspection Status: R Inspected By: Travis Coryea PE: 5892

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

24-1-1 Mirror or mirror backs are loose or improperly mounted.

28-1-2 Floor covering is missing, cut, loose, buckled, bulging or not secure.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.