

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                           |                        |              |                         |              |
|---------------------------------------|---------------------------|------------------------|--------------|-------------------------|--------------|
| <b>Type of Inspection:</b>            | Semi-Annual               | <b>Date:</b>           | 10/22/2014   | <b>Time:</b>            | 8:50 AM      |
| <b>Name of School Corporation:</b>    | UNION COUNTY SCHOOL CORP. | <b>Corp ID:</b>        | 817950       |                         |              |
| <b>Address of School Corporation:</b> | 107 Layman St             |                        |              |                         |              |
| <b>City:</b>                          | Liberty                   | <b>Zip:</b>            | 47353        | <b>County Number:</b>   | 81           |
| <b>VIN:</b>                           | 4UZAAXBV21CH83422         | <b>License Number:</b> | 1075         | <b>Bus Number:</b>      | 95           |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.  | <b>Year:</b>           | 2001         | <b>Make of Chassis:</b> | Freightliner |
| <b>Bus Type:</b>                      | C                         | <b>Mileage:</b>        | 144337       |                         |              |
| <b>Inspection Status:</b>             | O                         | <b>Inspected By:</b>   | Jeremy Mason | <b>PE:</b>              | 8139         |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 58-1-7                 | Optional rear stop arm device or school bus crossing arm criteria is not met |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                               |
|------------------------|--|
| 50-2-1                 | The service door does not open or close properly |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**