

## REPORT OF SCHOOL BUS INSPECTION

|  |                                   |   |
|--|-----------------------------------|---|
| <b>Type of Inspection:</b> Spot Checks                         | <b>Date:</b> 10/22/2014           | <b>Time:</b> 10:01 AM                         |
| <b>Name of School Corporation:</b> ANDERSON COMM. SCHOOL CORP. | <b>Corp ID:</b> 485275            |   |
| <b>Address of School Corporation:</b> 1600 Hillcrest Ave       |                                   |   |
| <b>City:</b> Anderson  | <b>Zip:</b> 46011                 | <b>County Number:</b> 48                      |
| <b>VIN:</b> 4DRBBAAP63B581691                                  | <b>License Number:</b> B695F      | <b>Bus Number:</b> 19                         |
| <b>Make of Body:</b> Blue Bird Corporation                     | <b>Year:</b> 2004                 | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Year:</b> 2002  | <b>Year:</b> 2002                 |   |
| <b>Bus Type:</b> C   | <b>Mileage:</b> 108315            |   |
| <b>Inspection Status:</b> O                                    | <b>Inspected By:</b> Jeremy Mason | <b>PE:</b> 8139                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 12-1-1                 | Clearance light is missing, cracked, faded, wrong color, or inoperative. |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 8-2-1                  | There is no brake certification, the certification has expired, or is not signed within the six month requirement.        |
| 21-2-2                 | There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire. |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**