

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/21/2014 Time: 9:24 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo Zip: 47140 County Number: 13
VIN: 4UZ6CFAA7XCA45441 License Number: B684E Bus Number: 10
Make of Body: Freightliner Year: 1999 Make of Chassis: Freightliner Year: 1999
Bus Type: C Mileage: 149613
Inspection Status: R Inspected By: Travis Coryea PE: 5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-2	Floor covering is missing, cut, loose, buckled, bulging or not secure.
24-1-1	Mirror or mirror backs are loose or improperly mounted.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.