

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	10/30/2014	Time:	6:11 AM
Name of School Corporation:	NORTHEAST SCHOOL CORPORATION	Corp ID:	777645		
Address of School Corporation:	PO Box 493				
City:	Hymera	Zip:	47855	County Number:	77
VIN:	4DRBWAAR38A503274	License Number:	11227	Bus Number:	3
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:	2008	Year:	2008		
Bus Type:	D	Mileage:	77817		
Inspection Status:	A	Inspected By:	Tyler VanNess	PE:	7583

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.