

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 11/5/2014	Time: 9:31 AM	
Name of School Corporation: MERRILLVILLE COMM. SCHOOL CORP	Corp ID: 454600		
Address of School Corporation: 6601 Delaware St			
City: Merrillville	Zip: 46410	County Number: 45	
VIN: 4DRBUAAN3DB255535	License Number: 3689	Bus Number: 4	
Make of Body: IC Corporation	Year: 2013	Make of Chassis: IC Corporation	Year: 2013
Bus Type: C	Mileage: 27614		
Inspection Status: R	Inspected By: Dale Morgan	PE: 4743	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.