

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|--------------------------------|-----------------|---------------|------------------|-----------|
| Type of Inspection: | Semi-Annual | Date: | 11/6/2014 | Time: | 9:55 AM |
| Name of School Corporation: | CRAWFORD CO. COMM. SCHOOL CORP | Corp ID: | 131300 | | |
| Address of School Corporation: | 5808 E Administration Rd | | | | |
| City: | Marengo | Zip: | 47140 | County Number: | 13 |
| VIN: | 1GBL7T1C01J509024 | License Number: | B951B | Bus Number: | 22 |
| Make of Body: | Blue Bird Corporation | Year: | 2002 | Make of Chassis: | Chevrolet |
| Bus Type: | C | Mileage: | 157079 | Year: | 2002 |
| Inspection Status: | R | Inspected By: | Travis Coryea | PE: | 5892 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 45-1-3 | Required padding is missing |
| 24-1-1 | Mirror or mirror backs are loose or improperly mounted. |
| 19-1-2 | Excessive effort is needed to open the emergency door. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.