REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	11/6/2014	Time:	9:55 AM
Name of School C	orporation:	CRAV	WFORD CO. CO	OMM. SCHOOL CO	RP	Corp ID:	131300
Address of School	Corporation:		5808 E Admin	stration Rd			
City:	Marengo		Zip:	47140		County Number:	13
VIN:	1GBL7T1C01J50902	4		License Number:	B951B	Bus Number:	22
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	Chevrolet	Year:	2002
Bus Type:	С			Mileage:	157079		
Inspection Status:	R		Inspected By:	Travis Coryea		PE:	5892

Violations - Rejected

Inspection Code	Description
45-1-3	Required padding is missing
24-1-1	Mirror or mirror backs are loose or improperly mounted.
19-1-2	Excessive effort is needed to open the emergency door.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.